



ESSX DBA XLOGIC SPORTS INC

7624 Pebble drive

Fort Worth Texas 76118

Toll Free (877) 367-3779

Fax (877) 329-3779

Cell (817) 819-1472

Bruce@xlogicsports.com

<http://www.officialESSX.com>

TO ALL IT MAY CONCERN:

ESSX poles do comply with the NFHS rules:

Since the year 2000 all poles have a weight label in addition to a permanent engraved area located at the butt of the pole near the pole tip. Prior to the year 2000 ESSX poles did not exist.

All ESSX vaulting poles will comply with the contrasting ring and viewable weight label NFHS rule. The ring with the 3/4" bold type will be located 3-4" down from the top of the pole as an indicator of the start of the grip area. Grip area known throughout the industry as an area of 12" located below the top handhold ring and weight label. Our weight label will have the serial number of the pole within its info to support that the pole matches the permanent engraved portion of the pole.

Any labels that will be replaced by ESSX will indicate the serial number of the pole. If the serial number located in the label does not match the permanent serial number of the pole the pole has been tampered with and should not be allowed to be used. The coach is responsible for maintaining the labels and during replacement is totally responsible for applying the label to the correct serial number pole. A fee of \$10.00 per label for replacement of the label may be imposed.

All ESSX Poles are tested before shipping to their customers. The coach and the athlete are responsible for the care of the fiberglass pole, no company provides a warranty replacement for broken poles.

Essx poles do fully meet and comply with any NFHS rules or interpretations.

Owner

Bruce Caldwell